

## Maintenance Advisory Reference

Entries in black are active advisories

Entries in red are archived advisories

Advisory #	Advisory Name	Notes
2019-02	Maintenance of Grade Separations on State Trunklines	Replaces MA 2002-04
2019-01	Discontinued Use of Breakaway Cable Terminals (BCTs)	Replaces MM 2003-01
2018-05	Maintenance Work Project	
2018-04	Guidance on Using Wing-Plow	Replaces MA 2017-02, MA 2014-01, MA 2008-06
2018-03	Disposing of Surplus and Unsuitable Soils	
2018-02	Storage of Materials Under Bridges and Structures	
2018-01	Discontinue Use of X-Lite Guardrail Terminal	
2017-02	Guidance on Using Wing-Plows	See MA 2018-04
2017-01	Maintenance Activity Guides-TAMS replacing MARS	
2014-01	Guidance on Using Wing-Plow	See MA 2018-04
2013-01	Best Practices for Applying Deicing Materials	
2012-04	Roadside Vegetation Management	
2012-03	PDRP	
2012-02	Cable Grip Slippage during Barrier Repair	
2012-01	Roadside-Spraying	
2010-05	Maintenance Material Reporting in LAPS	
2010-04	Insurance For Maintenance Subcontracts	
2010-03	High Tension Cable Barrier Repairs	Was part of research project, no longer needed
2010-02	Cable Barrier Turnbuckles	
2010-01	Oil-Water Separator	Information now located in Environmental Manuals
2009-11	Snow Plowing Near Railroad Crossings	
2009-10	Abrasives in Winter Operations	
2009-09	Cable Barrier System	
2009-08	Lights on Drums	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
2009-07	HMA Crack Treatment	Information incorporated into PCA for crack sealing and & concrete repair
2009-06	Edge Drains	
2009-05	Sign Sheeting Material Change	
2009-04	Illicit Discharge	
2009-03	Damaged Mailboxes	
2009-02	Calibration of salt trucks	
2009-01	White Shoulder Policy	
2008-10	Bridge Expansion Joints	Information located in Bridge Movement White Paper
2008-09	Disposal of Used Motor Oil	Information now located in Environmental Manuals
2008-08	Storage of Empty Drums	Information now located in Environmental Manuals
2008-07	Rest Area Lift Stations	
2008-06	Wing Plow	See MA 2018-04
2008-05	Liquid Deicing	
2008-04	Attenuator	No Longer applicable Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
2008-03	Emergency Scene	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
2008-02	Concrete Pavement	Information incorporated into PCA for crack sealing and & concrete repair
2008-01	Use of Arrow Panels	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
2007-01	Lights on Drums are Optional for Maintenance Activities	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual

2006-02	Mercury Switch Disposal	Information now located in Environmental Manuals
2006-01	Plastic Sign Substrates	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual
2005-02	Bridge Maintenance	Information located in Structural Concrete Repair White Paper
2005-01	Work Zone Safety	Information now located in Michigan Manual for Uniform Traffic Control Devices and the Work Zone Safety Mobility Manual

---